



Molina Upper Air Ventilation Report

Inspection Date: Spring 2021

HVAC systems brought up to ASHRAE standards using existing ventilation systems & additional filtration units

Room #	Area (sq. ft.)	Outside Air (CFM)	Occupancy Limit During COVID-19	Ready For Use
B200	400	181	12	Yes
2nd S Bathroom	100	Separate exhaust system		Yes
2nd S Bathroom	100	Separate exhaust system		Yes
B202	768	553	36	Yes
B203	704	644	42	Yes
B206	702	603	40	Yes
B207	684	583	38	Yes
B205	160	65	4	Yes
B204	121	57	3	Yes
Staff Lounge	231	251	16	Yes
a219	754	Filtration unit installed; 900 sq ft disinfected		Yes
a218	754	795	53	Yes
a217	783	399	26	Yes
215	810	436	29	Yes
a216	783	626	41	Yes
214	754	640	42	Yes

Molina Upper Air Ventilation Report

Inspection Date: Spring 2021

HVAC systems brought up to ASHRAE standards using existing ventilation systems & additional filtration units

Room #	Area (sq. ft.)	Outside Air (CFM)	Occupancy Limit During COVID-19	Ready For Use
a213	812	449	29	Yes
a212	754	517	34	Yes
2nd B Bathroom	125	Separate exhaust system		Yes
2nd G Bathroom	130	Separate exhaust system		Yes
A200	814	646	43	Yes
A201	360	101	6	Yes
a202	400	293	19	Yes
a203	720	361	24	Yes
a204	806	647	43	Yes
a206	754	407	27	Yes
a205	406	169	11	Yes
a213a	406	220	14	Yes
a208	754	494	32	Yes
a207	810	415	27	Yes
a209	783	619	41	Yes
a210	754	Filtration unit installed; 900 sq ft disinfected		Yes
a211	783	388	25	Yes
b105	684	462	30	Yes
b103	702	449	29	Yes
b104	160	70	4	Yes

Molina Upper Air Ventilation Report

Inspection Date: Spring 2021

HVAC systems brought up to ASHRAE standards using existing ventilation systems & additional filtration units

Room #	Area (sq. ft.)	Outside Air (CFM)	Occupancy Limit During COVID-19	Ready For Use
b102	704	531	35	Yes
b101	704	567	37	Yes
1st S Bathroom	150	Separate exhaust system		Yes
1st S Bathroom	165	Separate exhaust system		Yes
Gym	4400	1795	119	Yes
A122	754	589	39	Yes
a120	780	625	41	Yes
a121	667	524	34	Yes
a119	754	429	28	Yes
a116a	285	Storage area; Filtration unit not required		Yes
a116b	280	Storage area; Filtration unit not required		Yes
a118	690	528	35	Yes
a117	780	Filtration unit installed; 900 sq ft disinfected		Yes
a116	1050	406	27	Yes
a115	783	403	26	Yes
a113	280	386	25	Yes
a114	377	267	17	Yes
a112	644	521	34	Yes
Cafeteria	3186	1795	119	Yes
1st G Bathroom	220	Separate exhaust system		Yes

Molina Upper Air Ventilation Report

Inspection Date: Spring 2021

HVAC systems brought up to ASHRAE standards using existing ventilation systems & additional filtration units

Room #	Area (sq. ft.)	Outside Air (CFM)	Occupancy Limit During COVID-19	Ready For Use
1st B Bathroom	190	Separate exhaust system		Yes
a111	783	581	38	Yes
a109	870	397	26	Yes
a110	609	453	30	Yes
a108	754	Filtration unit installed; 900 sq ft disinfected		Yes
a107	667	423	28	Yes
a105	600	248	16	Yes
a104a	182	80	5	Yes
a104	1050	258	17	Yes
a106	870	432	28	Yes
a100	783	501	33	Yes
a100a	187	124	8	Yes
a100b	99	217	14	Yes
a100l	99	166	11	Yes
a100j	195	228	15	Yes
a100h	90	36	2	Yes
a100i	35	31	2	Yes
a100e	169	273	18	Yes
MS Bathroom	25	Separate exhaust system		Yes
MS Bathroom	25	Separate exhaust system		Yes

Molina Upper Air Ventilation Report

Inspection Date: Spring 2021

HVAC systems brought up to ASHRAE standards using existing ventilation systems & additional filtration units

Room #	Area (sq. ft.)	Outside Air (CFM)	Occupancy Limit During COVID-19	Ready For Use
a102	851	943	62	Yes
a101	840	538	35	Yes